Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0097**

Resource Identification

Property Name(s): ..... House, Route 635 {Function/Location}
Property Date: 1825
Address(s): ..... Route 635 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
other	other		
Porch	Porch - 1-story, 3-bay	Wood	Porch - Columns, Square
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Chimneys	Chimneys - Exterior end	Brick	other

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1825 ca {VDHR Survey File}
Accessed? .....
Primary Resource? ..... Yes
Number of Stories: 2.0
Architectural Style: ..... Other
Condition: .....
Interior Plan Type: ..... Central Passage, Single Pile
Threats to Resource: .....

Description: Architecture Summary: Simple Greek Revival cornice. Porch probably a victorian addition. Re-sided in asbestos shingles. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Dcmestic

Significance Statement: Good example of a modest, rural, Greek Revival I-house.

Bibliographic Documentation

Ownership Information

Report generated 11/17/04

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: ..... 1990/7 /4
Organization or Person: .... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-97
Negative no(s).

City/Town/Village/Hamlet Windsor Vicinity
Street address or route number Rte. 635, .3 mi. east of Rte. 610
Historic name
County Isle of Wight
U.S.G.S. Quad Windsor
Common name

Present use Dwelling
Original use Dwelling
Building Style Vernacular
Building Date(s) 2nd qtr., 19th century

1. Construction Materials

- [x] wood frame
- [ ] brick
  - bond: [ ] English [ ] Flemish [ ] ____-course American [ ] stretcher [ ] other ____
- [ ] stone
  - [ ] random rubble
  - [ ] coursed rubble
  - [ ] ashlar [ ] dressed [ ] rock-faced
- [ ] log:
  - [ ] squared [ ] unsquared
  - notching: [ ] V-notch [ ] saddle [ ] square [ ] half dovetail [ ] full dovetail [ ] diamond
- [ ] concrete block
- [ ] terra cotta
- [ ] steel frame
- [ ] other ____

2. Cladding Material

- [x] weatherboard
- [ ] vertical siding
- [ ] board & batten
- [x] shingle:
  - [ ] wood
  - [x] asbestos
  - [ ] asphalt
- [ ] bricktex
- [ ] other ____
- [ ] composition siding
- [ ] stucco
- [ ] aluminum or vinyl siding
- [ ] cast iron
- [ ] sheet metal
- [ ] enameled metal
- [ ] glass



3. Stories (number) 2
   - [ ] low basement
   - [ ] raised basement

4. Bays (number): front 3 side (church) ____
   - [x] symmetrical
   - [ ] asymmetrical

5. Roof Type
   - [ ] shed
     - [ ] parapet?
   - [x] gable
     - [ ] pediment?
     - [ ] parapet?
     - [ ] clipped end?
     - [ ] cross gable?
     - [ ] central front gable?
   - [ ] hipped
     - [ ] pyramidal?
   - [ ] mansard
   - [ ] false mansard
   - [ ] gambrel
   - [ ] flat
     - [ ] parapet?
   - [ ] roof not visible
   - [ ] other ____

6. Roofing Material
   - [ ] shingle
     - [ ] composition (asphalt, asbestos, etc.)
     - [ ] wood
   - [x] metal
     - [x] standing seam
     - [ ] corrugated
     - [ ] pressed tin (simulated shingles)
   - [ ] tile
     - [ ] pantile [ ] flat [ ] glazed
   - [ ] slate
   - [ ] not visible

7. Dormers (number): front ____ side ____
   - [ ] gable [ ] pediment?
   - [ ] shed
   - [ ] hipped

8. Primary Porch
   - style ____
   - stories 1
   - levels 1 bays 3
   - materials wood, standing-seam metal
   - description and decorative details: Hipped roof, square wood columns. Foundations & floor recently rebuilt. Porch probably Victorian addition.

9. General supplementary description and decoration:
   3-course American-bond brickwork, six-over-six sash. Simple Greek Revival cornice. Resided in asbetos shingles.

10. Major additions and alterations:
    Front and rear porches likely addition.

11. Outbuildings:

12. Landscape Features: Set in the center of corn fields with woods in background.

13. Significance:
    Good example of a modest rural, Greek Revival I house.

Surveyed by: Willie Graham Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey